


# Board of Visitor Facilities Tour



# Board of Visitor Facilities Tour



<b>George Marshall Hall GMH Building 62</b>	
1	Commence Tour @ MH 155
2	1st Floor - Room 178, active class room issues, work arounds
3	2nd floor roof view in library, roof view, solar panel view, and discussion - lightning protection
4	1st floor AHU Room (FY21/22 Heating System-BAS Project) 50% functional capacity
<b>Lincoln Hall Building 64</b>	
5	LH Cafeteria O&M services and future subway
6	LH Courtyard and water feature
7	LH Auditorium water leaks
8	LH Plaza pavers and concrete
9	Parking lot - drive cars to Roosevelt Hall parking area
<b>National War College - Roosevelt Hall Building 61</b>	
10	Parking area
11	Exterior Chiller Plant Cooling Towers + Fire Pump
12	View Building Envelope Issues - Façade + Roof
13	Central Lobby and general improvements
<b>Eisenhower Hall Building 59</b>	
14	5-10 Min General Brief 1st Floor - Review building renovation project - view key conditions-systems
	2nd floor general renovations
	3rd floor collaboration rooms - Mechanical repair/renovation
	3rd floor mechanical rooms and mold remediation